

532 Mass Ave, Boston

Miscellaneous window repair

Note: New window sash will be installed by others, except where window noted P.



532 Massachusetts Avenue
Boston, MA

Miscellaneous Window RESTORATION

Drawing 1

Front Elevation - NTS

All new front elevation head and jamb molding shall match existing wide moldings at basement windows. Both curved profile and flat head moldings are required.
New window sills shall be true mahogany or Spanish Cedar matching thickness of existing.

PRESERVATION TECHNOLOGY ASSOCIATES, LLC
SEPTEMBER, 2019

617 598 2255
jselwyn@preservationtechnology.net



**532 Massachusetts Avenue
Boston, MA**

**Miscellaneous Window RESTORATION
Drawing 2
NTS**


Repair Keynotes:

T - Provide new primed and two coat painted head and side jamb brick molding

S - Provide new primed and two coat painted window sill.

C - Replace sash cords with brass chain.

P - Prepare, prime and two coat paint ex. wood sash, replace loose, defective putty.




**532 Massachusetts Avenue
Boston, Ma**

**WINDOW MISCELLANEOUS RESTORATION
Drawing 3
NTS**

Repair Keynotes:

- T - Provide new primed and two coat painted head and side jamb brick molding
- S - Provide new primed and two coat painted window sill, mahogany or Spanish Cedar..
- C - Replace sash cords with brass chain.
- P - Prepare, prime and two coat paint ex. wood sash, replace loose, defective putty. Paint moldings



**532 Massachusetts Avenue
Boston, MA**

**Misc Window RESTORATION Drawing 3
NTS**

Repair Keynotes:

T - Provide new primed and two coat painted head and side jamb brick molding

S - Provide new primed and two coat painted window sill.

C - Replace sash cords with brass chain.

P - Prepare, prime and two coat paint ex. wood sash, replace loose, defective putty.

REAR ELEVATION

S - All windows . Provide new primed and two coated painted window sills.

Base Estimate on 30" window sills, standard thickness, clear pine.

Total - TEN rear elevation windows.

**532 Massachusetts Avenue
Boston, MA**

**Misc. Window RESTORATION Drawing 4
NTS**

END OF SPECIFICATION